

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Plunger Lift

6

Comment:

Corrective Action:

Date: _____

Type: Emission Control Device

2

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors

6

Comment:

Corrective Action:

Date: _____

Type: VRT

1

Comment:

Corrective Action:

Date: _____

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date: _____

Type: VRU

1

Comment:

Corrective Action:

Date: _____

Type: Compressor

1

Comment: Gas Lift

Corrective Action:

Date: _____

Type: Pig Station

2

Comment:

Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	automation / electric		
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLs	FIBERGLASS AST		,
Comment:	533 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	9	500 BBLs	STEEL AST		,
Comment:	533 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 446475 Type: WELL API Number: 123-43337 Status: PR Insp. Status: PR

Facility ID: 455341 Type: WELL API Number: 123-46994 Status: PR Insp. Status: PR

Facility ID: 455342 Type: WELL API Number: 123-46995 Status: PR Insp. Status: PR

Facility ID: 455343 Type: WELL API Number: 123-46996 Status: PR Insp. Status: PR

Facility ID: 455344 Type: WELL API Number: 123-46997 Status: PR Insp. Status: PR

Facility ID: 455345 Type: WELL API Number: 123-46998 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/02/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500582	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026645