

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2020

Submitted Date:

01/02/2020

Document Number:

699500595**FIELD INSPECTION FORM**Loc ID 431883 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	<a href="#">ALL INSPECTIONS</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431879	WELL	PR	03/01/2019	OW	123-36837	MATHEWS 4G-14H	PR
431880	WELL	PR	03/01/2019	OW	123-36838	MATHEWS 4E-14H	PR
431881	WELL	PR	10/24/2013	OW	123-36839	MATHEWS 4D-14H	PR
431882	WELL	PR	03/01/2019	OW	123-36840	MATHEWS 4F-14H	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: 6' Hog fence

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift

# 2

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead

# 4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 5

Comment: Automation / electric

Corrective Action:

Date:

Type: Pump Jack

# 2

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 431879 Type: WELL API Number: 123-36837 Status: PR Insp. Status: PRFacility ID: 431880 Type: WELL API Number: 123-36838 Status: PR Insp. Status: PRFacility ID: 431881 Type: WELL API Number: 123-36839 Status: PR Insp. Status: PRFacility ID: 431882 Type: WELL API Number: 123-36840 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/02/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500596	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026652</a>