

Well Name: Davis MV 1A      API #    05-067-08478  
Well Name: Davis FR 1A      API #    05-067-08481  
Well Name: IGS 155            API #    05-067-09578

Inspection Number:    693900300

**Corrective Action:**    Storm water erosion along the eastern edge of the location, flows are not sufficiently de-energized and wattles are no longer functioning

**Correction Action Due:**

**Action Completed:**    6/5/2019

**Action Taken:**        Install additional wattles and clean out and re-enforce other wattles along eastern edge of location,

**Corrective Action:**    Storm water erosion along access road where rock velocity checks are not slowing flow velocity sufficiently

**Correction Action Due:**

**Action Completed:**    6/5/2019

**Action Taken:**        Repair, clean out and add more rock velocity checks along access road, install rock rundown at culvert outlet at the bottom of the hill.

**Corrective Action:**    Russian knapweed observed along the eastern edge of the location and along the access road.

**Correction Action Due:**    6/15/2019

**Action Completed:**    6/12/2019

**Action Taken:**        Sprayed for noxious weeds along the eastern edge of the location and along the access road.

