

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2020

Submitted Date:

01/02/2020

Document Number:

679706786

**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐  
 336042 Moran, Rick 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296064	WELL	PR	06/01/2013	GW	103-11290	FREEDOM UNIT 297-16A1	PR
296065	WELL	PR	12/01/2017	GW	103-11289	FRFREEDOM UNIT 297-16A5	PR
296066	WELL	PR	06/01/2013	GW	103-11288	FREEDOM UNIT 297-16A4	PR
296067	WELL	PR	06/01/2013	GW	103-11287	FREEDOM UNIT 297-16A2	PR
296068	WELL	PR	06/01/2013	GW	103-11286	FREEDOM UNIT 297-16A3	PR
296069	WELL	PR	06/01/2013	GW	103-11285	FREEDOM UNIT 297-16A6	PR
296070	WELL	PR	11/01/2017	GW	103-11284	FREEDOM UNIT 297-16A10	PR
296071	WELL	PR	05/01/2018	GW	103-11283	FREEDOM UNIT 297-16A7	PR
296072	WELL	PR	06/01/2013	GW	103-11282	FREEDOM UNIT 297-16A8	PR
296073	WELL	PR	07/01/2013	GW	103-11281	FREEDOM UNIT 297-16A9	PR

**General Comment:**[COGCC Inspection Report Summary.](#)

On 1-2-2020 at approximately 12:25, inspector Rick Moran, conducted a routine well inspection at XTO Energy well pad Freedom Unit 297-16A in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679706786.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Communication building and well manifold.		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Containers of SCI-8760 with secondary containment.		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	296064	Type:	WELL	API Number:	103-11290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296065	Type:	WELL	API Number:	103-11289	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296066	Type:	WELL	API Number:	103-11288	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296067	Type:	WELL	API Number:	103-11287	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296068	Type:	WELL	API Number:	103-11286	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296069	Type:	WELL	API Number:	103-11285	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296070	Type:	WELL	API Number:	103-11284	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	296071	Type:	WELL	API Number:	103-11283	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	296072	Type:	WELL	API Number:	103-11282	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID:	296073	Type:	WELL	API Number:	103-11281	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706787	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5027156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5027156</a>