

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2020

Submitted Date:

01/02/2020

Document Number:

679706788**FIELD INSPECTION FORM**Loc ID 335717 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276625	WELL	PR	06/01/2013	GW	103-10555	LOVE RANCH 8 FEE G1	PR
276786	WELL	PR	03/01/2014	GW	103-10558	LOVE RANCH 8 FEE G 4	PR
276789	WELL	PR	07/01/2013	GW	103-10557	LOVE RANCH 8 FEE G3	PR
276790	WELL	PR	07/01/2013	GW	103-10556	LOVE RANCH 8 FEE G2	PR
277180	WELL	PR	04/01/2017	GW	103-10559	LOVE RANCH 8 FEE G5	PR
278393	WELL	PR	03/01/2014	GW	103-10599	LOVE RANCH 8 FEE G8	PR
278395	WELL	PR	02/01/2014	GW	103-10601	LOVE RANCH 8 FEE G7	PR
279109	WELL	PR	07/01/2013	GW	103-10616	LOVE RANCH 8 FEDERAL G10	PR
279344	WELL	PR	07/01/2013	GW	103-10621	LOVE RANCH 8 FEDERAL G9	PR
298252	WELL	PR	02/01/2014	GW	103-11379	LOVE RANCH 8 FEE G6A	PR

**General Comment:**[COGCC Inspection Report Summary.](#)[On 1-2-2020 at approximately 12:45, inspector Rick Moran, conducted a routine well inspection at XTO Energy well pad Love Ranch 8 Fee 6 in Rio Blanco county.](#)[No corrective actions were identified.](#)[This is a summary of inspection report 679706788.](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Chemical / solar.		
Corrective Action:		Date:	

**Equipment:**

Type: Other	# 3		corrective date
Comment:	Pump building, battery / solar, and well manifold.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Four containers of SCI-8760 and 1 container of Multisweet MX 765-8 with secondary containment.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	276625	Type:	WELL	API Number:	103-10555	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	276786	Type:	WELL	API Number:	103-10558	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	276789	Type:	WELL	API Number:	103-10557	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	276790	Type:	WELL	API Number:	103-10556	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	277180	Type:	WELL	API Number:	103-10559	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	278393	Type:	WELL	API Number:	103-10599	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	278395	Type:	WELL	API Number:	103-10601	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	279109	Type:	WELL	API Number:	103-10616	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

Facility ID:	279344	Type:	WELL	API Number:	103-10621	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID:	298252	Type:	WELL	API Number:	103-11379	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706789	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5027157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5027157</a>