

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2020

Submitted Date:

01/03/2020

Document Number:

696101766**FIELD INSPECTION FORM**Loc ID 310742 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296787	WELL	TA	07/17/2018	OW	123-26907	NORTH PLATTE 33-13	TA
427867	WELL	SI	05/01/2019	OW	123-35139	North Platte S-13	SI
427878	WELL	TA	08/14/2012	OW	123-35146	North Platte 34-13	TA

General Comment:

This is WELL inspection.

Well(s): 2: Temporarily Abandoned | TA ; 1: Shut-In | SI.

Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (319357, 310742).

(Well(s): 3: Temporarily Abandoned | TA ; 1: Shut-In | SI).

Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357
for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	3: wellsites.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type				
Comment:	3: wellsites. Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 3			corrective date
Comment:	3: wellsites. Appears plumbed to surface.			
Corrective Action:				Date:
Type:	#			
Comment:	Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Other	# 1			

Comment:	North Platte 33-13: Wellhead: w/ Master & casing valves.				
Corrective Action:				Date:	
Type: Plunger Lift		# 2			
Comment:	North Platte 34-13, S-13.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.394166,-104.381339	
Comment:	Centralized Battery serves 2 Location IDs (319357, 310742). Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 296787 Type: WELL API Number: 123-26907 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: [Temporarily Abandoned | TA.](#)
[Form 4 doc. #401705845 indicates TA status: 11/14/2017. Plugged back. Approved.](#)
[Form 21-MIT doc. #401474307, MIT done: 11/30/2017. Approved.](#)

Corrective Action: Date: Facility ID: 427867 Type: WELL API Number: 123-35139 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: [Shut-In | SI.](#)
[COGCC records indicate last production: 04/2019.](#)

Corrective Action: Date: Facility ID: 427878 Type: WELL API Number: 123-35146 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: [Temporarily Abandoned | TA.](#)
[Form 4 doc. #402066882 indicates TA status: 08/14/2014. Plugged back. Approved.](#)
[Form 21-MIT doc. #401126637, MIT done: 09/20/2016. Approved.](#)

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 01/03/2020 at approximately 11:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /33-13 Location ID: 310742 Well Names: North Platte 33-13, North Platte 34-13, North Platte S-13 API: 05-123-26907, 05-123-35146, 05-123-35139 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 2: Temporarily Abandoned TA ; 1: Shut-In SI. Battery: Shut-down Inactive.</p> <p>Centralized Battery serves 2 Location IDs (319357, 310742). (Well(s): 3: Temporarily Abandoned TA ; 1: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696101764 and/or Location ID #319357 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/03/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101767	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5028290