

Pit Status Evaluation Form

Pit Overview:

Pit Name: BOX ELDER 1	Facility ID: 114261
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: MACEY & MERSHON OIL INC / 52225	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: BOX ELDER FARMS #1 (API 05-001-08351, Facility ID 202946, Loc ID 320186)	

County: ADAMS			
Township: 1S	Range: 65W	Section: 22	QQ: SENE
Original Latitude/ Longitude: 39.95198 / -104.643054			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698091 | Date: 3/26/1985 |
| | Doc #: 698088 | Date: 11/9/1989 |
| | Doc #: 894009 | Date: 10/25/1999 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314528 | Date: 1/1/1996 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspections and pit inventory report document a concrete water vault and tinhorn then a fiberglass tank on location. Pit status has been changed to Closed.

