



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at Gas Engine, see photos		
Corrective Action:	Properly dispose of oily waste in accordance with 907.e	Date:	01/21/2020

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 301987 Type: WELL API Number: 123-30162 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Winter conditions, snow covered ground in some spots at the time of inspection. Stained Soil at gas engine, see photos.</a>	petrie	01/06/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301075	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5029134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5029134</a>