

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/03/2020

Submitted Date:

01/03/2020

Document Number:

699500603

FIELD INSPECTION FORM
 Loc ID 434216 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434211	WELL	PR	06/16/2014	OW	123-38025	HIGHWAY 160 37N-2HZ	PR
434212	WELL	PR	06/28/2014	OW	123-38026	HIGHWAY 160 15C-2HZ	PR
434213	WELL	SI	01/01/2019	OW	123-38027	HIGHWAY 160 38N-2HZ	SI
434214	WELL	PR	06/16/2014	OW	123-38028	HIGHWAY 160 15N-2HZ	PR
434215	WELL	PR	05/01/2019	OW	123-38029	HIGHWAY 160 16C-2HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: Red AG fencing / 4' Barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: VRT

1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

4

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

7

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

10

Comment: Automation/electric

Corrective Action:

Date:

Type: LACT

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

5

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: VRU

2

Comment:

Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities				
Facility ID: <u>434211</u>	Type: <u>WELL</u>	API Number: <u>123-38025</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434212</u>	Type: <u>WELL</u>	API Number: <u>123-38026</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434213</u>	Type: <u>WELL</u>	API Number: <u>123-38027</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>434214</u>	Type: <u>WELL</u>	API Number: <u>123-38028</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434215</u>	Type: <u>WELL</u>	API Number: <u>123-38029</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>PR</u>			
Corrective Action:				Date: <u> </u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/03/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500604	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5029483