

Inspection Photos
Operator Name: Caerus Piceance LLC
Location: 335622



Well head and repaired Flowline. Well was producing at time of inspection