



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Luis Guerrero (l.guerrero@kosinm.com) |
| Submission Date: | Jan 6, 2020 12:59:23 PM MST |
| Server Receive Date: | Jan 6, 2020 12:59:31 PM MST |
| Reference Number: | 20200106-18128759193 |
| Location: | 17401 US-550, Aztec, NM 87410, USA Jan 6, 2020 12:58:35 PM MST [View Map] |

Information

| | |
|-----------------|---|
| Name | l.guerrero@kosinm.com |
| Date | Dec 27, 2019 |
| Well Name | JACQUEZ, THOMAS GAS UNIT A 2 |
| API Number | 50670849600 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Install Rock Run Down |

Photo of first corrective action completed



Completed work description Corrective Action 1

Rock armored erosional channel

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed



Completed work description of corrective action 3
Completed work description of corrective action 4
Summary of all work completed

Installed rock armored silt bowl with rock armored
rundown to prevent erosion.