

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2020

Submitted Date:

01/07/2020

Document Number:

693901297

**FIELD INSPECTION FORM**

Loc ID 306774 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263958	WELL	PR	03/13/2018	GW	067-08733	LARSEN 01-12 2	RI

**General Comment:**

On 1/6/2020 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

- Weeds need to be controlled at the appropriate time and no later than 5/1/2020.
- Debris needs to be removed by 1/31/2020. Management of weeds (such as mowing) is needed to prevent debris.

See below, and attached photos for additional detail.

**Inspected Facilities**

Facility ID: 263958 Type: WELL API Number: 067-08733 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment Debris from dried kochia, up to 2.5 feet tall, observed within the project area.

Corrective Action Remove and properly dispose of weed debris. Weeds need to be managed (ie mowed) during the growing season to prevent debris dispersal.

Date 01/31/2020

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use?      In      Production areas stabilized ?       
 1003c. Compacted areas have been cross ripped?       
 1003d. Drilling pit closed?      Subsidence over on drill pit?       
 Cuttings management:       
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?       
 Production areas have been stabilized?      Segregated soils have been replaced?     

RESTORATION AND REVEGETATION

Cropland

Top soil replaced      Recontoured      Perennial forage re-established     

Non-Cropland

Top soil replaced      Recontoured      80% Revegetation     

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

1003 f. Weeds Noxious weeds?     

Comment Approximately 200 Canada thistles observed within the eastern project area. Although location is largely snow covered perennial grasses such as intermediate wheatgrass and smooth brome observed.

Corrective Action Control weeds at the appropriate time and no later than 5/1/2020.

Date 05/01/2020

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:      Date Final Reclamation Completed:     

Final Land Use:     

Reminder:     

Comment:

Well plugged      Pit mouse/rat holes, cellars backfilled     

Debris removed      No disturbance /Location never built     

Access Roads Regraded      Contoured      Culverts removed     

Gravel removed     

Location and associated production facilities reclaimed      Locations, facilities, roads, recontoured     

Compaction alleviation      Dust and erosion control     

Non cropland: Revegetated 80%      Cropland: perennial forage     

Weeds present      Subsidence     

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA%       
 TRANSECT RESULTS OF REFERENCE AREA%       
 TOTAL % OF DESIRABLE VEGETATION COVER       
 VEGETATIVE COVER     

Comment:

Corrective Action:

Date

Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	--	--

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: A detailed stormwater assessment was not conducted due to snow cover. Operator should assess erosion and site stabilization upon soil thaw/snow melt.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693901298	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030028">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030028</a>