

Well Name: Elsa 34-6-19 1 **API #** 05-067-09922
Well Name: Elsa 34-6-19 2 **API #** 05-067-09945
Inspection Number: 693900408

Corrective Action: Repair/maintain and replace perimeter controls around the perimeter of the well pad where needed. Installation, repair, and maintenance should be conducted in accordance with good engineering practices such as those described in the CDOT stormwater control manuals.

Correction Action Due: 7/26/2019

Action Completed: 11/27/2019

