

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo1 loc pic



Photo 2 unused equipment

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 3 Trash




Photo 4 Trash

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 5 Unused equipment (cement pad)



Phtoto 6 ECD's

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 7 Unused Unmarked not LOTO riser



Photo 8 Unused Unmarked not LOTO riser

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 9 Unused equipment: H brace



Photo 10 Meter house

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 11 Unused equipment



Photo 12 Unused equipment

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718




Photo 13 unused equipment



Photo 14 Stained soil and mechanical issue 1" valve leaking

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718




Photo 15 Stained soil on side of LACT Building



Photo 16 Stained soil What appears to be oil and water in containment due to leak on 3" line.

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 17 3" hammer Union leaking off production tanks



Photo 18 Stained soil next to production tanks.

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Colorado Oil and Gas Conservation Commission
39.94502, -104.835, 1511.1m
Jan 7, 2020 13:44:25

Photo 19 Stained soil under recirc pump and trash dirty rags.



Colorado Oil and Gas Conservation Commission
39.94505, -104.83499, 1514.8m
Jan 7, 2020 13:45:19

Photo 20 Unused equipment heater house and canvas next to VRT

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 21 Stained soil around recirc pump



Stained 22 soil around oil tanks.

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 23 Stained soil around VRU compressor



Photo 24 Unused equipment: Electric cables next to low pressure separator

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 25 Stained soil under heater of HOZ sew



Photo 26 Mechanical issue: 2" VLV leaking on HOZ sep

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 27 Unused equipment next separators



Photo 28 Unused equipment next separators

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 29 loc pic



Photo 30 loc pic

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 31 2536-1-4HC and 2413-3-15HN WH



Photo 32 unused equipment: Cattle panels

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 33 Unused equipment: tubing and cattle panels



Photo 34 WH

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 35 WH



Photo 36 WH

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 37 WH and unused equipment T-Posts



Photo 38 Unused equipment Tools

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 39 TNK BTRY



Photo 40 Crude oil tank no placards

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 41 Crude oil tank no placards



**Photo 42 Three fiberglass produced water tanks no placards. 1
Steel maintenance tank no placards . Maintenance tank not
painted**

Inspection Photos
Location Name: Schaefer Pad
Location ID: 440718



Photo 43 Topsoil pile and area next to fence appears to be seeded and crimped .