

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/07/2020

Submitted Date:

01/07/2020

Document Number:

699500638**FIELD INSPECTION FORM**
 Loc ID 462021 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
James, Brian		bjames@hpres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462016	WELL	XX	02/13/2019		123-49713	Grinde 01-64-05 0108C	DG
462017	WELL	XX	02/13/2019		123-49714	Grinde 01-64-05-1724C	DG
462018	WELL	XX	02/13/2019		123-49715	Grinde 01-64-05 1609B	DG
462019	WELL	XX	02/13/2019		123-49716	Grinde 01-64-05-3225C	DG
462020	WELL	XX	02/13/2019		123-49717	Grinde 01-64-05-1724B	DG

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: <u>462016</u>	Type: <u>WELL</u>	API Number: <u>123-49713</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>462017</u>	Type: <u>WELL</u>	API Number: <u>123-49714</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>462018</u>	Type: <u>WELL</u>	API Number: <u>123-49715</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>462019</u>	Type: <u>WELL</u>	API Number: <u>123-49716</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>462020</u>	Type: <u>WELL</u>	API Number: <u>123-49717</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>

**Well Drilling**

**Rig:** Rig Name: Cade Drilling LLC 23 Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: NO Unlined Pit: NO Closed Loop: YES Semi-Closed Loop: NO  
 Multi-Well: YES Disposal Location: \_\_\_\_\_

Comment: At time of inspection Drilling rig crew was in process of POOH with drill pipe

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/07/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500639	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030862</a>