

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/13/2019

Submitted Date:

01/06/2020

Document Number:

698600179

FIELD INSPECTION FORM

Loc ID 312151 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10380
Name of Operator: BENCHMARK ENERGY LLC
Address: PO BOX 8747
City: PRATT State: KS Zip: 67124

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219053	WELL	TA	01/01/1999	ERIW	075-05875	NW GRAYLIN (LOGAN J 12-2W) (OWP) 2-W	PA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of flow line abandonment task.
Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.
See link at end of report for path to downloadable pictures.

Inspected Facilities

Facility ID: 219053 Type: WELL API Number: 075-05875 Status: TA Insp. Status: PA

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Well was previously plugged and abandoned with flow line left in place.	stjohnw	01/03/2020
Flow line was hooked into vacuum truck and trapped fluids were removed. Line was excavated and flow line cut off approximately 4' below grade. Line cement plugged and excavation backfilled and dressed. Flow line abandonment for location is complete. Site is ready for final reclamation task.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600198	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032553