


Dover Atwood Corporation (#10626) - COGCC Inspection Photos 1/7/2020

Well: Bear Creek 1-3

API # 009-06598



Signage at facility/ battery; Information not fully legible.



View from meter run to wellhead located approximately 1270' west of facility/ battery.

Dover Atwood Corporation (#10626) - COGCC Inspection Photos 1/7/2020

Well: Bear Creek 1-3

API # 009-06598



View of facility/ battery. Earthen berms have eroded; inadequate berm capacity. Trash (pallet) on location.



View of wellhead looking west from facility. Off location flowline runs between wellhead and facility; approximately 1270' in length.

