

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2020

Submitted Date:

01/09/2020

Document Number:

696301105

**FIELD INSPECTION FORM**

Loc ID 431194 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 410 17TH STREET SUITE #1400  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">ALL INSPECTIONS</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431192	WELL	SI	09/01/2019	OW	123-36467	State Antelope O-K-24HNB	SI
431195	WELL	PR	05/01/2019	OW	123-36468	State Antelope 44-41-24HNB	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate (x2)		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Tubing and Rod Strings, see photo 3		
Corrective Action:	Comply with Rule 603.f		Date: <u>02/10/2020</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Pump Jack	# 2			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Generator			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 2			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 2			

Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLS	STEEL AST		40.379270,-104.266050
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 431192 Type: WELL API Number: 123-36467 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 431195 Type: WELL API Number: 123-36468 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Wednesday 01/08/2020 at approximately 12:49, I, Inspector Erica Petrie, conducted a Field Inspection at Bonanza Creek Energy Operating Company LLC, State Antelope T-24 PAD, Location ID #431194 in Weld County, Colorado.                      While there, I observed Production Operations.                      During this inspection the following possible compliance issues were observed:                      Unused Tubing and Rod Strings south of wells. See photo 3. Comply with Rule 603.f.                      Corrective Action date 02.10.2020                      A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.                      Continuing Educational Inspections</p>	petrie	01/09/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301106	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032763</a>