



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:	bent rebar by electric panel area		
Corrective Action:	Comply with 603.f	Date:	01/16/2020
Type	DEBRIS		
Comment:	Dead weeds around wellsite		
Corrective Action:	Comply with Rule 603.f	Date:	01/16/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric panel area steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 0		corrective date
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, transformers and meterbox		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241028 Type: WELL API Number: 123-08816 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 1/9/2020 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:                      Tom L. Russell #2 at API #05-123-08816 in Weld County Colorado.                      While there, I observed producing wellsite.                      During this inspection the following compliance issues were observed:                      603.f housekeeping: dead weeds around wellsite, CA date 1/16/2020 see photos 2 and 3.                      603.f housekeeping: Trash(bent rebar) by electric panel area, CA date 1/16/2020 see photo 4.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	01/09/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300887	wellsite pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5032865</a>