

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2020

Submitted Date:

01/09/2020

Document Number:

690101636

FIELD INSPECTION FORMLoc ID 321151 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Gray, Mike		mgray@xeogc.com	
Welsh, Brian		brian.welsh@state.co.us	
Hahn, Mike		mhahn@xeogc.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Stevens, Amy		astevens@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206158	WELL	PR	08/01/2018	GW	009-06574	GODFREY 1-19	EG

General Comment:

COGCC Engineering Integrity Inspection; The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline and signs/ markers sections of report. Photos uploaded.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Signage from previous operator at wellhead; Inaccurate operator information at wellhead.		
Corrective Action:	Install sign at wellhead to comply with Rule 210.b.	Date:	02/10/2020
Type	TANK LABELS/PLACARDS		
Comment:	Open top tank missing labels		
Corrective Action:	Install tank labels to comply with Rule 210.d.	Date:	02/10/2020
Type	BATTERY		
Comment:	Signage from previous operator at battery; Inaccurate operator information at battery.		
Corrective Action:	Install sign at battery to comply with Rule 210.b.	Date:	02/10/2020

Emergency Contact Number:

Comment: Corrective Action:

Date: 02/10/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 206158 Type: WELL API Number: 009-06574 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment:

This well is currently producing.
 The off location flowline (wellhead line) runs approximately 1060' west from the wellhead to facility/ battery adjacent to the east side of CR 42. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by West Texas Operating Co with off location flowlines.

Corrective Action:

Comply with the following COGCC rule (partial description):
 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101638	Inaccurate signage at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033025
690101640	View east from facility to well; inaccurate signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033026
690101641	Open top tank missing labels	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033027