

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	chainlink topped with barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	exposed at surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259663 Type: WELL API Number: 123-20363 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 1/9/2020 at approximately 1335 hrs. I, Inspector Robbie Revas, conducted an on-site inspection at HSR-Teets #3-29A Kerr McGee, at API# 123-20363 in Weld County Colorado. While there, I observed a producing well site, this is a follow up inspection per Doc. # 699300428 During this inspection the following possible compliance issue appears to have been addressed: 603.f Housekeeping: Debris /dead weeds around location see photos. No follow up on this site inspection needs to be conducted compliance issues appear to have been corrected to comply with COGCC rules. This is a summary of inspection report</p>	revasr	01/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300890	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033104