

Response to December 2, 2019 Inspection
Document Number 696501182

COGCC conducted an inspection of the Schaefer 13-14F location (Location ID 327830) on December 2, 2019 (Document 696501182). During that inspection, COGCC made the following observations:

Trash Comment: Broken concrete next to tank berm. Comply with Rule 603.f.

Tanks and Berms Comment: Secondary containment is inadequate to contain largest single tank plus sufficient freeboard. Repair or install berms or other secondary containment devices per Rule 605.a.(4)

Response: Noble removed debris from the site (603.f.). The berm surrounding the crude oil tank and the produced water pit was repaired to provide adequate secondary containment [605.a.(4)]. The repaired secondary containment provides adequate storage of the largest single tank and sufficient freeboard to contain precipitation.

Name: Schaefer 13-14F

Location ID: 327830

COGCC conducted a follow-up inspection of the Schaefer 13-14F location (Location ID 327830) on December 2, 2019 (Document 696501182). During that inspection, COGCC made the following observations:

1. Trash: Broken concrete next to tank berm. Comply with Rule 603.f.
2. Tanks and Berms: Secondary containment is inadequate to contain largest single tank plus sufficient freeboard. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

COGCC – 12/02/2019



Photo 1. Wellhead

Noble Energy – 01/08/2020



Photo NBL1. Facility location

Name: Schaefer 13-14F

Location ID: 327830

COGCC conducted a follow-up inspection of the Schaefer 13-14F location (Location ID 327830) on December 2, 2019 (Document 696501182). During that inspection, COGCC made the following observations:

2. Tanks and Berms: Secondary containment is inadequate to contain largest single tank plus sufficient freeboard. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

COGCC – 12/02/2019



Photo 2. Production Facility

Noble Energy – 01/08/2020



Photo NBL2. Production facility, facing northeast. Secondary containment has been repaired to provide adequate containment per 605.a.(4).

Name: Schaefer 13-14F

Location ID: 327830

COGCC conducted a follow-up inspection of the Schaefer 13-14F location (Location ID 327830) on December 2, 2019 (Document 696501182). During that inspection, COGCC made the following observations:

2. Tanks and Berms: Secondary containment is inadequate to contain largest single tank plus sufficient freeboard. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

COGCC – 12/02/2019



Photo 3. Crude oil tank berm

Noble Energy – 01/08/2020



Photo NBL3. Berm surrounding crude oil tank and produced water pit, facing northeast. Secondary containment has been repaired to provide adequate containment per 605.a.(4).

Name: Schaefer 13-14F

Location ID: 327830

COGCC conducted a follow-up inspection of the Schaefer 13-14F location (Location ID 327830) on July 11, 2017 (Document 682402392). During that inspection, COGCC made the following observations:

1. Trash: Broken concrete next to tank berm. Comply with Rule 603.f.

COGCC – 12/02/2019



Photo 4. Trash

Noble Energy – 01/08/2020



Photo NBL4. Trash has been removed from the site.