

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2020

Submitted Date:

01/10/2020

Document Number:

690101633

FIELD INSPECTION FORM

Loc ID 321088 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Crane, Rocky	(719) 529-0682	rockycrane@yahoo.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206014	WELL	PR	07/19/1991	GW	009-06430	BRYAN 1-18	EG

General Comment:

[COGCC Engineering Integrity Inspection; The Corrective Actions identified during this COGCC \(EG\) field inspection are located in the flowline section of report. Photos uploaded.](#)

Inspected Facilities

Facility ID: 206014 Type: WELL API Number: 009-06430 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: Material:
 Variance: Age: Contents: Produced Water

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment:

This well is currently producing.
 The off location flowline (produced water dump flowline/ from wellhead) runs approximately 2065' north from the wellhead to an open top tank adjacent to the south side of CR BB (at 37.35309, -102.086434). This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

 Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Dover Atwood Corporation with off location flowlines.

Corrective Action:

Comply with the following COGCC rule (partial description):

 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101646	Bryan 1-18 Aerial Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033804
690101647	Wellhead and sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033805
690101665	Open top tank and sign; view south toward wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033806