

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2020

Submitted Date:

01/10/2020

Document Number:

690101666

**FIELD INSPECTION FORM**

Loc ID 321694 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 51065  
Name of Operator: LOEB LLC\* HERMAN L  
Address: P O BOX 838  
City: LAWRENCEVILLE State: IL Zip: 62439

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hafele, Jeremy		jeremy@loeboil.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Pelton, Shane	620-617-5870	shane@loeboil.com	
Middagh, Jesse		jesse@loeboil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207803	WELL	PR	10/01/2019	OW	017-06738	WHITE AL 2	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Pump Jack		# 1		
Comment:	Lufkin 320			
Corrective Action:				Date:
Type: Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:				Date:
Type: Ancillary equipment		# 2		
Comment:	Electric panel and cathodic rectifier			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 207803 Type: WELL API Number: 017-06738 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment:

This well is currently producing.  
 The off location flowline (wellhead line) runs approximately 1300' W-NW from the wellhead to a shared facility/ central tank battery for White AM-1, AL-1, AL-2 wells @ 38.820350/-102.059280. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.  
  
 Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Herman L. Loeb LLC with off location flowlines.

Corrective Action:

Comply with the following COGCC rule (partial description):  
  
 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101667	Aerial Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034036</a>
690101668	Signage at pump jack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034037</a>
690101669	View W-NW from well to battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034038">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034038</a>