

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2019

Submitted Date:

01/10/2020

Document Number:

698600197

**FIELD INSPECTION FORM**

Loc ID 312208 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10380  
Name of Operator: BENCHMARK ENERGY LLC  
Address: PO BOX 8747  
City: PRATT State: KS Zip: 67124

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219514	WELL	TA	01/26/2016	ERIW	075-06449	MOUNT HOPE UNIT (OWP) W-7	TA

**General Comment:**

This is an orphaned well inspection. Inspection completed to document well status prior to start of plug and abandonment task.  
Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.  
See link at end of report for path to downloadable pictures.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	COGCC contact sticker.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	COGCC contact stricker.		
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Concrete chunks in the SW corner of location.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Flow Line	# 2			
Comment:	Located (2) riser.			
Corrective Action:		Date:		
Type: Deadman # & Marked	# 2			
Comment:	Located (2) anchors.			
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	Wellhead with tree.			
Corrective Action:		Date:		

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 219514 Type: WELL API Number: 075-06449 Status: TA Insp. Status: TA

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Concrete chunks in SW corner of location maybe removed during scheduled well P&A task.	stjohnw	01/03/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600220	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034309">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034309</a>