

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2020

Submitted Date:

01/13/2020

Document Number:

699800382

FIELD INSPECTION FORM

Loc ID 334074 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 34720
 Name of Operator: GORDON ENGINEERING INC
 Address: PO BOX 3525
 City: GRAND JUNCTION State: CO Zip: 81502

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Gordon, John	(970) 618-0811	johngordon1gordon@yahoo.com	
,Engineering		dnr_cogccengineering@state.co.us	
, Kellerby		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221806	WELL	SI	02/01/2017	GW	077-08408	FEDERAL 32-1	SI

General Comment:

[COGCC Inspection Report Summary](#)
 On Monday 1/13/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, conducted a follow up inspection at GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW, Location #334074 in Mesa County Colorado.
 Refer to document #696600130 inspection performed on 6/13/19. Not all corrective actions have been completed.
 During this inspection the following possible compliance issues were observed: Multiple holes in tank containment liner. See photo #0393 with a previous corrective action date of 5/6/19. Perform required MIT on well. With a previous corrective action date of 4/16/19.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:	60 bbl capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Multiple holes in tank containment liner. See photo #0393			
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Patch all hole in tank containment liner.			Date: 05/06/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221806 Type: WELL API Number: 077-08408 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well last produced November 2016. Meter run disconnected. No MIT on record.

Corrective Action: Preform Mechanical integrity test on well.

Date: 04/16/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						
		Gravel				
		Compaction				
		Berms				
		Culverts				
Compaction						
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699800383	Photos for Insp. #699800382	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036369