

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

699300863

**FIELD INSPECTION FORM**

Loc ID 435889 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435888	WELL	PR	08/31/2014	OW	123-38826	SCOTT 27N-32HZ	PR
435890	WELL	PR	07/01/2019	OW	123-38827	SCOTT 26N-32HZ	PR
435891	WELL	SI	10/01/2019	OW	123-38828	SCOTT 1C-32HZ	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank on well pad does not indicate contents or volume.		
Corrective Action:	comply with Rule 210.d	Date:	02/08/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 3		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Automation		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: <u>435888</u>	Type: <u>WELL</u>	API Number: <u>123-38826</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action:		Date:
Facility ID: <u>435890</u>	Type: <u>WELL</u>	API Number: <u>123-38827</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action:		Date:
Facility ID: <u>435891</u>	Type: <u>WELL</u>	API Number: <u>123-38828</u>	Status: <u>SI</u> Insp. Status: <u>SI</u>
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____			
Comment: <u>SI</u>	Corrective Action:		Date: _____

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 1/8/2020 at approximately 1005 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Scott 1C-32Hz at Location #435889</p> <p>in Weld County Colorado.                      While there, I observed a multi well wellsite.                      During this inspection the following compliance issue was observed:                      210.d Signs and Markers Tanks: Tank on wellsite does not show contents or volume. CA                      date 2/8/2020 see photo 7.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	01/08/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402280432	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031084</a>
699300864	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031075</a>