

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2020

Submitted Date:

01/15/2020

Document Number:

696900087

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: CHESSON, BOB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
2 Number of Corrective Actions

- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 10548  
Name of Operator: HRM RESOURCES II LLC  
Address: 410 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	303-893-6621	tpape@hrmres.com	Operation Engineer
Allison, Rick		rick.allison@state.co.us	
Medina, Justin		justin.medina@state.co.us	
, TROY	713) 818-8152	tmouret@p3petro.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

**General Comment:**

Inspection for complaint #200448545 .According to complaint "The Gilberts have also seen evidence of hydrocarbons on the ground around the tank battery located in the SE corner of 18 1S60W."

Minor hydrocarbon stains observed as shown on attached inspection photos. I observed no other evidence of any reportable E&P waste spill or releases.

Fence along CR 49/lease access road obstructing access to 05-001-06084 and 05-001-06133. Move fence or provide alternate wellsite access.

Comply with Rule 603.f regarding unused equipment/supplies.

Chemical storage must comply with Rule 1002 for chemical storage and spill containment.

See attached inspection photos.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	TB sign obscured with documents.		
Corrective Action:	Remove documnts obscuring sign.	Date:	01/30/2020

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Chemical storage and unused equipmnet.		
Corrective Action:	Chemicals must have secondary/spill containment. Comply with rule 603.f.	Date:	02/29/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**COGCC Comments**

Comment	User	Date
<p>Inspection for complaint #200448545 .According to complaint "The Gilberts have also seen evidence of hydrocarbons on the ground around the tank battery located in the SE corner of 18 1S60W."</p> <p>Minor hydrocarbon stains observed as shown on attached inspection photos. I observed no other evidence of any reportable E&amp;P waste spill or releases.</p> <p>Fence along CR 49/lease access road obstructing access to 05-001-06084 and 05-001-06133. Move fence or provide alternate wellsite access.</p> <p>Comply with Rule 603.f regarding unused equipment/supplies.</p> <p>Chemical storage must comply with Rule 1002 for chemical storage and spill containment.</p>	chessonr	01/15/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696900091	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038754">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5038754</a>