

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2020

Submitted Date:

01/16/2020

Document Number:

700600057

**FIELD INSPECTION FORM**

Loc ID 333736 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1801 BROADWAY SUITE 350  
City: DENVER State: CO Zip: 80202

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262233	WELL	PR	09/14/2012	GW	071-07546	DROWSEY DUCK 43-30	EI
264454	PIT	AC	08/20/2002		-	DROWSEY DUCK 43-30 ONSITE	AC
266001	WELL	PA	07/29/2016	GW	071-07808	DROWSEY DUCK 43-30 TR	EI

**General Comment:**

Desktop review showed Remediation 9866 submitted for closure of pit 264454 appears to have been intended for pit 270534.  
Field inspection confirms pit 270534 was closed and pit 264454 is open and active.  
Changed Remediation 9866 from 264454 to pit 270534 and closed 270534 in COGCC database.

**Inspected Facilities**

Facility ID: 262233 Type: WELL API Number: 071-07546 Status: PR Insp. Status: EI

Facility ID: 264454 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 266001 Type: WELL API Number: 071-07808 Status: PA Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 264454      Lat: 37.141321      Long: -104.815488

Reference Point: SE      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600058	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039691">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039691</a>