

# Inspection Photos

API: 05-017-07813

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 1/14/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-017-07813 | Date: 1/14/2020

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road.



## Inspection Photos



**Photo 2.** Facing north toward the location. The perimeter of the location is fenced.



## Inspection Photos



**Photo 3.** Facing toward the topsoil pile at the west side of the location. Surface roughening has occurred around the perimeter.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07813 | Date: 1/14/2020

## Inspection Photos



**Photo 4.** Topsoil pile at west side of the location has been tracked in. The soils are sandy and susceptible to wind erosion. Additional BMP's will be needed for stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07813 | Date: 1/14/2020

## Inspection Photos



**Photo 5.** Well sign posted at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07813 | Date: 1/14/2020

## Inspection Photos



**Photo 6.** North side of the location facing south.

