

Inspection Photos

API: 05-017-07718

Operator: VECTA OIL & GAS

Inspection Date: 1/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 1. Facing north toward the location. The perimeter of the location is fenced and this cattle guard remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 2. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 3. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 4. View of vegetation cover at the western portion of location. Photo shows predominately undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 5. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020

Inspection Photos



Photo 6. Center of the location facing east. Native vegetation is established well at the east portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07718 | Date: 1/14/2020