

Inspection Photos  
Operator: BP America  
Location/API #: 067-07686  
Date: 1-15-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward.



Photo 3. View of the southeastern project area from the well pad entrance facing eastward. It appears that cobble is placed in erosional channel in response to 2018 corrective action. Operator should note that cobble rock is not considered a BMP, as it does not effectively reduce energy of stormwater flows. Course rock is needed where rock is used as a stormwater BMP. Operator needs to continue to monitor stormwater erosion and apply BMPs according to good engineering practices when/where stabilization is needed.





Photo 4. View of the northern project area from the northeastern corner facing westward.



Photo 5. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.