

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2020

Submitted Date:

01/17/2020

Document Number:

689901644

FIELD INSPECTION FORM

Loc ID 467285 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55098
Name of Operator: MCCOY PETROLEUM CORPORATION
Address: 9342 EAST CENTRAL
City: WICHITA State: KS Zip: 67206-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
HAMPEL SCOTT		scott@mccoypetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467643	WELL	XX	09/20/2019		017-07813	ALC 1548 1-23	CI

General Comment:

This is a Location Construction Inspection.

(This area is currently blank for additional notes or observations.)

Location Construction

Location ID: 467643 CDP: _____

Comment: It appears topsoil was adequately salvaged at the location.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: Vehicle and equipment will need to be kept to the minimum needed for operation.

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes	Vehicle Trakcing	Yes`

Comments: Erosion BMPs: Surface roughening was performed around the perimeter of the location. Additional BMP's may be needed along the downslope portion of the pad.

Other BMPs: The soils are sandy and susceptible to erosion. Tracking was performed on the topsoil piles however, this will not stabilize and protect the topsoil. Topsoil piles will need to be seeded and stabilized.

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901645	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041195