

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2020

Submitted Date:

01/17/2020

Document Number:

699800421

FIELD INSPECTION FORM

Loc ID 334511 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1401
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| , Laramie | | cogccnotifications@laramie-energy.com | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 278102 | WELL | PR | 04/23/2014 | GW | 077-08900 | ESPERANZA 8-6 | PR |
| 278410 | WELL | PR | 12/17/2005 | GW | 077-08913 | ESPERANZA 8-5 | PR |
| 278411 | WELL | PR | 10/13/2015 | GW | 077-08912 | ESPERANZA 8-10 | PR |
| 278497 | WELL | PR | 04/23/2014 | GW | 077-08916 | ESPERANZA FEDERAL 8- | PR |
| 278498 | WELL | PR | 02/09/2016 | GW | 077-08915 | ESPERANZA FEDERAL 8- | PR |
| 278499 | WELL | PR | 10/09/2005 | GW | 077-08914 | ESPERANZA FEDERAL 8- | PR |

General Comment:

[COGCC Inspection Report Summary](#)
On Friday 1/17/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Esperanza /8-6 Pad, Location #334511 in Mesa County Colorado.
While there, I observed normal production operations.
This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|-----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--------|--|-------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|---------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Heated Separator | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Tanks and Berms: | | | | | | |
|-------------------------|----------|---------------------|---------------------|-------------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 4 | 300 BBLs | STEEL AST | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 278102 | Type: | WELL | API Number: | 077-08900 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278410 | Type: | WELL | API Number: | 077-08913 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278411 | Type: | WELL | API Number: | 077-08912 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278497 | Type: | WELL | API Number: | 077-08916 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278498 | Type: | WELL | API Number: | 077-08915 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278499 | Type: | WELL | API Number: | 077-08914 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | | | | | |
| | | Gravel | | | | |
| | | Berms | | | | |
| | | Compaction | | | | |
| Ditches | | | | | | |
| Gravel | | | | | | |
| | | Culverts | | | | |
| Compaction | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 699800422 | Photos for Insp. #699800421 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041565 |