

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2020

Submitted Date:

01/12/2020

Document Number:

688306732**FIELD INSPECTION FORM**Loc ID 316934 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233291	WELL	PR	03/01/2016	OW	121-05320	COLORADO STATE 1	PR

General Comment:Pit Inspection

Inspector noticed that the eastern pit level was high and that the north and south berms were recently maintained (two pits at this location). See attached photos of the south berms, an erosion rill and white stained soil that goes from the bottom of the southeast berms and NE into the winter wheat field. This pit berm has failed in the same location before and produced water has spilled into the field. Two neighbors stopped by while inspector was at the pits and said that the berms had failed recently and produced water went into the field. One of the neighbors told the inspector that he would like his water well that is 160' deep sampled. Inspector contacted COGCC EPS, RY, on 1/8/2020 and he said that would do an inspection the next week. Inspector also contacted operator on 1/8/2020.

Inspected Facilities									
Facility ID:	233291	Type:	WELL	API Number:	121-05320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Oct 2019 production reported to COGCC database.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: dryland crop fieldCorrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: NOComment: Eastern pit's water level was high on the SE cor and a freeboard marker should be installed to monitor this.Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.Date: 01/31/2020Type: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Inspector Name: Sherman, Susan

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	western pit	Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402283054	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034937
688306733	Investment Equipment Colorado State 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034934