

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402007348

Date Received:

04/12/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Harkins, Liz</u>	<u>303-233-2232/719-429-4513</u>	<u>Lharkins@austinexploration.com</u>
<u>Goss, Aaron</u>	<u>303-495-0327</u>	<u>agoss@fremontpetroleum.com</u>
<u>Hart, Tim</u>		<u>thart@fremontpetroleum.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Del Hierro, Chris</u>	<u>720-431-7468</u>	<u>chris@CDHconsult.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900038

Inspection Date: 02/27/2019

FIR Submit Date: 03/07/2019

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 451507

Location Name: Bird Number: 13-18 County: FREMONT

Qtrqr: NWS Sec: 18 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.306211 Longitude: -105.160133

FACILITY - API Number: 05-043-00 Facility ID: 451506

Facility Name: Bird Number: 13-18

Qtrqr: NWS Sec: 18 Twp: 20S Range: 69W Meridian: 6
W

Latitude: 38.306211 Longitude: -105.160133

CORRECTIVE ACTIONS:

1 ☒ CA# 123031

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/10/2019

Operator Comment: In accordance with Rule 1002.f., Stormwater controls and BMPs have been installed within the project area. BMPs consisting of swale repair, ditch repair, rock check dams, straw wattles, recontouring, and additional roughening and hydromulch/hydroseed have been installed and/or repaired, as necessary.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hierro

Signed:

Title: Agent

Date: 4/12/2019 9:25:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402007348	FIR RESOLUTION SUBMITTED
402007369	Various BMPs
402007370	Former road, roughened and hydromulched/hydroseeded
402007371	Swale, wattle, hydroseed, and rock check dams
402007372	vegetative recovery, wattles and rock check dams
402007373	Wattle, swale, hydroseed, rock check dams
402007374	headcut erosion repair, wattles, seeding, rock check dams

Total Attach: 7 Files