

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402009564

Date Received:

04/15/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Goss, Aaron</u>	<u>303-495-0327</u>	<u>agoss@fremontpetroleum.com</u>
<u>Hart, Tim</u>		<u>thart@fremontpetroleum.com</u>
<u>Harkins, Liz</u>	<u>303-233-2232/719-429-4513</u>	<u>Lharkins@austinexploration.com</u>
<u>Del Hierro, Chris</u>	<u>720-431-7468</u>	<u>chris@CDHconsult.com</u>
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900044

Inspection Date: 02/28/2019

FIR Submit Date: 03/11/2019

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 429883

Location Name: Pathfinder Number: C 14-01 1 County: FREMONT

Qtrqr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.333410 Longitude: -105.179460

FACILITY - API Number: 05-043-00 Facility ID: 429882

Facility Name: Amerigo Vespucci Number: 1

Qtrqr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.333410 Longitude: -105.179460

CORRECTIVE ACTIONS:

1 CA# 123106

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff, Jason Kasola (719) 574-8602 (office) or (719) 641-0291 (cell).

Date: 03/13/2019

Response: CA COMPLETED

Date of Completion: 03/27/2019

Operator Comment: Per Rule 906.a., de minimis volume of what appeared to be mud and salt crust were scraped/excavated from near the wellhead and near the frac tank to three inches below grade. Excavation/scraping occurred on 3/25/19 and material was removed on 3/27/19. Jason Kosola was notified via FIRR Document #401987365 on 3/27/19 and again via email on 4/15/19. As the material was of a very small volume, a Form 19 has not been submitted. However, the 4/15/19 email inquires as to whether a Form 19 is preferred.

COGCC Decision: **Not Approved**

COGCC Representative:

[Empty box for COGCC Representative signature]

2 CA# 123107

Corrective Action: Install stormwater controls along the access road to control stormwater run-on and runoff and prevent erosion.

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 04/15/2019

Operator Comment: In accordance with Rule 1002.f., stormwater Best Management Practices (BMPs) have been installed, repaired, or maintained as necessary along the access road. Stormwater control and erosion prevention measures include grading, recontouring, ditch installation, rock check dams, straw wattles, hydromulching and hydroseeding.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty box for COGCC Representative signature]

OPERATOR COMMENT AND SUBMITTAL

Comment:

[Empty box for Operator Comment]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hierro

Signed:

Title: Agent

Date: 4/15/2019 10:30:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402009564	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files