

Construction and Stormwater Inspection

January 10 and 16, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 470396

Inspection Document #: 697501034

Weld County, CO

SWNW Section 18 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 1. Photo taken from the Northern perimeter of the location on January 10, 2020, facing South. Photo illustrates the beginning of a ditch and berm BMP; however, Operator had not yet completed installing the BMP at the time of this inspection.



Photo 2. Photo taken from the Southwestern perimeter of location on January 10, 2020, facing East. Photo illustrates a ditch and berm BMP in the foreground. In the background sediment trap BMPs installation.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 3. Photo taken from the southern location on January 10, 2020, facing Northeast. See comments under Photo 1 regarding the ditch and berm BMP.



Photo 4. Photo taken from the eastern perimeter of location on January 10, 2020, facing Northwest. See comments under Photo 1 regarding the ditch and berm BMP.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 5. Photo taken from the Northeastern perimeter of location on January 10, 2020, facing North. Photo illustrates a hydro excavation operation. Operator is trying to delineate where an irrigation tile drainage is located so damage does not occur when installing the sound walls.



Photo 6. Photo taken from the Northeastern perimeter of location on January 10, 2020, facing West; towards Larimer County Road 1. See comments under Photo 1 regarding the ditch and berm BMP.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 7. Photo taken from the Northern perimeter of location on January 16, 2020, facing South. Photo illustrates Operator conducting topsoil salvage operations along the eastern portion of location.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 8. Photo taken from the Northern perimeter of location on January 16, 2020, facing Southwest. Photo illustrates the current topsoil stockpile located along the southern perimeter of location.



Photo 9. Photo taken from the Northwestern perimeter of location on January 16, 2020, facing Southeast. Operator has completed the installation of the ditch and berm BMP. Operator has stabilized the berm portion of the BMP with equipment tracking.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 10. Photo taken from the Northwestern perimeter of location on January 16, 2020, facing South. See comments under Photo 9 regarding the ditch and berm BMP. Operator still in-process of installing inlet/outlet protection for the above culvert.



Photo 11. Photo taken from the entrance of location on January 16, 2020, facing West. Photo illustrates that entrance has pre-existing gravel. Operator will likely be required to install additional tracking device BMPs once more equipment is mobilized to location.

Inspection Photos
Location Name: DAMORE /5-18HZ Pad
Location ID: 470396



Photo 12. Photo taken from the entrance of location on January 16, 2020, facing East. Photo illustrates a temporary sign and mailbox with the approved Form 2A per the Form 2A Conditions of Approval.