

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2020

Submitted Date:

01/21/2020

Document Number:

696101924

**FIELD INSPECTION FORM**

Loc ID 331446 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262092	WELL	SI	04/01/2019	OW	123-20697	SKURICH/ROTHE 6A	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment removed.  
Reclamation progressing w/ mulching.  
Abandoned Battery SE corner GPS coordinates: 40.423155, -104.476273

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Pig Station	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Plugged & Abandoned   PA. Equipment removed.				
Corrective Action:					Date:

**Paint**

Condition:

Other (Content):

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width: 100px;" type="text"/>

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

**Flaring:**

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

**Inspected Facilities**

Facility ID: 262092 Type: WELL API Number: 123-20697 Status: SI Insp. Status: PA

**Workover**

Comment: Plugged & Abandoned | PA.  
Well appears to be cut / capped.  
Form 6 doc. #402181417 indicates plugging date: 08/23/2019. Approval Pending.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary:</a></p> <p>On TUE 01/21/2020 at approximately 14:54 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: SKURICH/ROTHER-65N63W /6SE                      Location ID: 331446                      Well Name: Skurich/Rothe 6A                      API: 05-123-20697                      Location County: Weld County, Colorado                      Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. ALL equipment removed.                      Reclamation progressing w/ mulching.                      Abandoned Battery SE corner GPS coordinates: 40.423155, -104.476273</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/21/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101925	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044315">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044315</a>