

Inspection Photos

API: 05-071-09381

Operator: XTO ENERGY INC

Inspection Date: 1/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 1. Facing north at the beginning of the access road. Additional rock rip/rap has been installed along the side of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 2. Facing toward the side of the access road as it ascends up the steep grade. Rock rip/rap and check dams have been installed along the road. The sides of the slope have been seeded and hydro mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 3. Facing northwest along the access road toward the location. The access will remain per the approved variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 4. The culvert outlet has been cut closer to the surface and rock rip/rap outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 5. Facing northwest toward the location which has been recontoured and reclaimed. The location has been hydromulched and stormwater controls are installed around the perimeter and drainage areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 6. Facing south down the hillside toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 7. Facing southwest toward the top portion of the location where the cut slope was previously located. The location is recontoured and matches the surrounding contour of the terrain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 8. Facing southeast near the bottom of the location. Stormwater controls are installed along the side of the road and perimeter of the location Stormwater is directed toward the culvert at this point.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 9. Standing at the bottom of the location facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 10. Standing at the bottom of the location facing north. The soils were properly tracked and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019

Inspection Photos



Photo 11. Standing at the bottom of the location facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09381 | Date: 1/22/2019