

McLaughlin 72
API: 05-103-01143
Inspection: 679707043



Photo 1. Excavated Location.

Well bore

McLaughlin 72
API: 05-103-01143
Inspection: 679707043



Photo 2. Well bore.

McLaughlin 72
API: 05-103-01143
Inspection: 679707043



Photo 3. Well marker.



Photo 4. Wood used to plug well bore in ~1953.

McLaughlin 72
API: 05-103-01143
Inspection: 679707043



Photo 5. Surface casing installed 1-22-2020 to plug well.



Photo 6. New surface casing installed.