

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2020

Submitted Date:

01/23/2020

Document Number:

679707052

FIELD INSPECTION FORM

Loc ID 398968 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 27900
Name of Operator: EQUITY OIL CO
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspections
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199941	WELL	AL	11/11/1911	LO	103-40201	MCLAUGHLIN 64	PA

General Comment:

[COGCC Inspection Report Summary.](#)

On 1-23-2020 at approximately 11:45, inspector Rick Moran, conducted a follow up inspection at Equity Oil well McLaughlin 64 in Rio Blanco county of FIR document 679707045

Note: The 3 cubic foot gas collection bag placed at the top of the casing collected no measurable volume of gas after 22.5 hours. No popping sound was heard during this inspection. No gas odor detected. The prior day every ~10 seconds a very slight sound like a tiny gas bubble popping was heard at the cemented top of the casing.

This is a summary of inspection report 679707052.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type OTHER		
Comment:	Temporary orange		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 199941 Type: WELL API Number: 103-40201 Status: AL Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was drilled in 1953 with no record of production.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679707053	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5046195