


## Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



**Photo #0453 from entrance to location**



**Photo #0458 Debris in tank containment.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



**Photo #0454 Multiple holes in tank containment liner.**




**Photo #0455 Multiple holes in tank containment liner.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LINDAUER-68S96W /3SWSE

Location ID: 334105



**Photo #0457 Multiple holes in tank containment liner.**