

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2020

Submitted Date:

01/24/2020

Document Number:

694500165

FIELD INSPECTION FORM

 Loc ID: 428531
 Inspector Name: NEIDEL, KRIS
 On-Site Inspection:
 2A Doc Num:

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

 OGCC Operator Number: 95520
 Name of Operator: WESCO OPERATING INC
 Address: 120 S DURBIN STREET
 City: CASPER State: WY Zip: 82602

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428531	LOCATION	AC			-	Maudlin Gulch Tank Battery	EI
451105	SPILL OR RELEASE	CL	07/26/2017		-	Maudlin Gulch Tank Battery	EI
467136	SPILL OR RELEASE	AC	09/03/2019		-	Maudlin tank battery	EI

General Comment:

On 1/8/2020 COGCC staff, Kris Neidel was present to witness the groundwater investigation that is a part of Remediation Project #14686 at the Maudlin tank battery. Weather was 25 degrees and cloudy. Upon arrival, Wesco was measuring depth to groundwater in second boring in the area east of the tank battery. 0'-4' was potholed with hydrovac, 4'-6' was fine sand, 6'-10' was sandy shale, 10'-13' was moist sandy shale, 15' was wet silty soil. A static water level was measured at (approximately 4.5'). After a consult with Wesco, HRL and COGCC it was determined that the well should be completed at this TD. The well was cased with pvc and screened at a shallow depth to intercept the shallow static water level. A rainbow sheen was observed in water that was bailed from the well. The rig was mobilized to the third boring on the north side of the former soil storage area. The hole was potholed with a hydrovac to 3 feet. 3'-12' had grey silty clay (clay appeared to have hydrocarbon impact, a sample was collected per rule 910.B.3.b), 12'-15' had signs of ground water as moist clay, 14-16 feet appeared to be tan clay soil, 16'-18' was clay. The well was screened from 22'-7' and completed as "MW-2". No water samples were collected, it is expected that water samples will be collected the week of 1/27/2020.

Inspected Facilities

Facility ID: 428531 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 451105 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 467136 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500166	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5046782