

Inspection Photos

API: 05-043-40006

Operator: JAVERNICK OIL

Inspection Date: 1/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing southeast toward the location. There is cement debris that remains shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 2. Close up view of the cement debris found at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 3. Facing south where well was located. This area is bare of vegetation and must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 4. There are cement block and cemented anchor that remain at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 5. Facing north where well was located. This area is bare of vegetation and must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020

Inspection Photos



Photo 6. The access road made a circle around the well site. There is still gravel that remains and areas bare of vegetation along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40006 | Date: 1/23/2020