

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-----------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | Date: | <input type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | | # | | corrective date |
|--------------------|---|-----|-------|-----------------|
| Type: Flow Line | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Bradenhead | | # 1 | | |
| Comment: | Bradenhead valve is exposed at surface. | | | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Other | | # 1 | | |
| Comment: | Rig pump and tank are grounded | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 250809 Type: WELL API Number: 123-18612 Status: PR Insp. Status: WK

Cement

Cement Contractor

Contractor Name: A-Plus

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Hold safety meeting, MIRU Cutters e-line, load and pressure test csg to 560 psig with no pressure loss, release pressure, RIH and perforate csg @ 2499' KB 6 SPF and 2000' KB 6 SPF for annular squeeze, POOH with spent gun, RIH with CICR and set @ 2125' GL, POOH with setting tool, RDMO e-line, TIH with stinger and tbg, sting into CICR, hold safety meeting, RU A-Plus Well Service cementers, attempts to establish circulation and condition annulus were unsuccessful, RD cementers, POOH with tbg and stinger, SIW, SDFN.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Seeding | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696501563 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5047855 |