

Inspection Photos

API: 05-043-06059

Operator: JAVERNICK OIL

Inspection Date: 1/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing southeast toward the access road. This area of the former road is bare of vegetation and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 2. There is erosion occurring down the former road. The erosion channels need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 3. There is an erosion gully along the road that is approximately 2-3 ft. deep.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 4. Vegetation is establishing along the remainder of the road to the location. Arrow points to area that may need erosion control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 5. Facing west toward the location. Vegetation is well established at the location and consist of Indian rice grass and Sand dropseed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020

Inspection Photos



Photo 6. Facing east toward the location. Vegetation is well established at the location and consist of Indian rice grass and Sand dropseed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06059 | Date: 1/23/2020