

# Inspection Photos

Operator: Catamount Energy  
Location/API #: 067-05279  
Date: 1-22-2020



Photo 1. View of the project area from the northern edge of the adjacent well pad, facing center.



Photo 2. View of the eastern project area from the southeastern portion facing northward. Although snow covered, it is apparent that revegetation is not conducted and erosion/stormwater controls are not installed.