

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2020

Submitted Date:

01/27/2020

Document Number:

688306838**FIELD INSPECTION FORM**Loc ID 457751 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 35080Name of Operator: GRAND MESA OPERATING COAddress: 1700 N. WATERFRONT PKWY BL 600City: WICHITA State: KS Zip: 67206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reilly, Pat	316-265-3000	preilly@gmocks.com	Designated Agent
Reilly, Pat	316-265-3000	preilly@gmocks.com	Designated Agent
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457750	WELL	XX	10/03/2018		121-11081	The Undeclared 1-7	DG

**General Comment:**Surface Cementing Inspection

**Inspected Facilities**Facility ID: 457750 Type: WELL API Number: 121-11081 Status: XX Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Murfin/wwrig120 Pusher/Rig Manager: Mike Polley  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO  
 Multi-Well: NO Disposal Location: on location

**Comment:** Surface TD 496', pipe set at 486' kb, 12 1/4" hole, 8 5/8" 24 pipe-strap welded first 3 joints, tack welded the rest (SAE)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Cement****Cement Contractor**

Contractor Name: HSI Contractor Phone: \_\_\_\_\_

**Surface Casing**

Cement Volume (sx): 300 Circulate to Surface: YES  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

**Intermediate Casing**

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Production Casing**

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Plugging Operations**

Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

**Comment:** Class A, 2% gel, 3% CaCl

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			Material Handling And Spill Prevention	Pass	
Slope Roughening	Pass					
Berms	Pass	Culverts	Pass	Covering Materials	Pass	

Comment: pasture, Gordon Creek is east of location (see attached photo)Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Water FreshLined: YESPit ID: Lat: 39.626100Long: -103.000000Reference Point: SEOther: Length: Width: **Lining:**Liner Type: HDPELiner Condition: AdequateComment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: Comment: Corrective Action: Date: Type: Drilling PitLined: NOPit ID: Lat: 39.626240Long: -103.367480Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment:

Inspector Name: Sherman, Susan

Corrective Action		Date:
<b>Netting:</b>		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective Action		Date:

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306851	Grand Mesa The Undefeated 1-7	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048234</a>