

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2020

Submitted Date:

01/27/2020

Document Number:

689803667**FIELD INSPECTION FORM**
 Loc ID 312827 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------|---------------------------------|
| Fillpot, Greg | (307) 299-3829 | gfillpot@hilcorp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 222530 | WELL | PR | 08/01/2019 | GW | 081-05546 | DUNCAN UNIT 2 1 | PR |

General Comment:[COGCC Inspection Report 689803667 Summary](#)

On Friday 01/24/2020 at approximately 13:45, I, Inspector Emily Waldron, conducted a field inspection at Hilcorp Energy Company Duncan Unit 2 1, at 05-081-05546 in Moffat County Colorado.

While there, I observed Production.

This is a summary of inspection report 689803667.

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 713-209-2400

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|------------|---|----------|------------------|---------|--------|--|
| CONDENSATE | 1 | 200 BBLs | HEATED STEEL AST | | , | |

| | |
|----------|--|
| Comment: | |
|----------|--|

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|-----------|----------|--|
| Condition | Adequate | |
|-----------|----------|--|

| | |
|-----------------|--|
| Other (Content) | |
|-----------------|--|

| | |
|------------------|--|
| Other (Capacity) | |
|------------------|--|

| | |
|--------------|--|
| Other (Type) | |
|--------------|--|

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|-------|----------|---------------------|---------------------|-------------|--|
| Earth | Adequate | | | Adequate | |

| | |
|----------|--|
| Comment: | |
|----------|--|

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------|----|--|--|
| Yes/No | NO | | |
|--------|----|--|--|

| | | | |
|----------|--|--|--|
| Comment: | | | |
|----------|--|--|--|

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | |
|----------|--|
| Comment: | |
|----------|--|

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 222530 | Type: | WELL | API Number: | 081-05546 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 689803668 | Inspection Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048577 |